



NPS54-82-004

NAVAL POSTGRADUATE SCHOOL Monterey, California



EVALUATION OF MAINTAINABILITY ENHANCEMENT

FOR TCP/TSP REVISION 6.0 UPDATE .20

Norman F. Schneidewind

February 1982

Final Report: 1 Jan 80 to 1 Jan 82

Approved for public release; distribution unlimited

Prepared for:

The Trident Command and Control Systems Maintenance Agency Newport, Rhode Island

82 05 19 014

SELECTE DAY 1 8 1982

NAVAL POSTGRADUATE SCHOOL Monterey, California

Rear Admiral J. J. Ekelund Superintendent

David R. Schrady Acting Provost

The work reported herein was supported by the Trident Command and Control Systems Maintenance Agency.

Reproduction of all or part of this report is authorized.

This report was prepared by:

Election

Professor of Computer Science

Reviewed by:

Released by:

CARL R. JONES, Chairman

Administrative Sciences Department

Dean of Research

Jantification

DTIC

COPY

BY________

Distr bition/

Accession For NTIS CPASI DTIC TAB . Unannameed

Avail th Litty Codes

TORING CARD 1. 1.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER 2. GOVT	ACCESSION NO. J. ECIPIENT'S CATALOG NUMBER
NPS54-82-004	H114 476
4. TITLE (and Subtitie)	S. TYPE OF REPORT & PERIOD COVERE
EVALUATION OF MAINTAINABILITY ENHANC	EMENT Final Report
FOR TCP/TSP REVISION 6.0 UPDATE .20	1 Jan 80 to 1 Jan 82
	6. PERFORMING ORG. REPORT NUMBER
. AUTHOR(e)	8. CONTRACT OR GRANT NUMBER(*)
Norman F. Schneidewind	
PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Naval Postgraduate School	N4216680WR00007
Monterey, California 93940	N4210000W200007
1. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
Trident Command and Control Systems	22 February 1982
Maintenance Agency	13. NUMBER OF PAGES
Newport, Rhode Island 02840	ntrolling Office) 15. SECURITY CLASS, (of this report)
14. MONITORING AGENCY NAME & ADDRESS/II different from Co.	Unclassified
	15a. DECLASSIFICATION/DOWNGRADING
	SCHEDULE
17. DISTRIBUTION STATEMENT (of the abetract entered in Block	20, Il dillerent irem Report)
18. SUPPLEMENTARY NOTES	
19. KEY WORDS (Continue on reverse elde if necessary and identify	
	AVINST 3560.1 PUB 38
•	STD 1679
Traceability	
10. ABSTRACT (Continue on reverse side if necessary and identity	ha Mach cumber)

to overlay a structured documentation technique on programs which are inherently non-structured (written in low-level language and patched)

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE 5/N 0102-014-6601

Unclassified
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

discussed. Discrepancies which arose between the newly constructed charts and the original listings are highlighted. A conclusion of this study is that rather than improving clarity, applying structured documentation to non-structured programs may result in the opposite effect--incomplete, inconsistent, and ambiguous documentation--because a hierarchical format cannot adequately represent a non-hierarchical program.

SECNAVINST 3560.1 and MIL-STD 1679 (Navy) are considered by CCSMA to be relevant documents for maintenance purposes. Therefore, the documentation system was checked for conformance with applicable sections of 3560.1 and 1679. In addition, the documentation system was compared with applicable sections of FIPS PUB 38, published by the National Bureau of Standards. Although officially FIPS PUB 38 applies to ADP and not to embedded computer systems, it provides good guidelines for program documentation and maintenance. It was found that 6.0/.20 does not include coverage of many of the applicable sections of the three documents.

SUMMARY

the "Maintainability Enhancement for TCP/TSP Revision 6.0 Update .20," referred to as 6.0/.20. The approach for accomplishing this task was to compare 6.0/.20 for compliance or conformity with applicable sections of SECNAVINST 3560.1, FIPS PUB 38, AND MIL-STD 1679. In addition, a sample of 6.0/.20, Volume 2, was examined in some detail for its usefulness as a software maintenance tool in terms of consistency, completeness, understandability, and absence of errors. Many suggestions for improvement have been made.

Our conclusions are that 6.0/.20:

- Does enhance maintainability. However, we believe listings alone, even if they are structured, are inadequate for maintenance purposes.
- Does not include coverage of significant applicable items called for in 3560.1, FIPS PUB 38, and 1679.
- Appears to be incomplete and to contain a moderate amount of inconsistencies, ambiguities, and errors.
- Could provide an excellent software maintenance tool if its quality were improved in accordance with the suggestions made in this report.

TABLE OF CONTENTS

			Page	No.
	SUMI	4ARY		1
ı.	INT	RODUCTION		5
	A.	Purpose		5
	в.	Approach		5
	c.	Scope		7
II.	EVA	LUATION OF 6.0/.20	•	10
	A.	With Respect to SECNAVINST 3560.1,	•	10
		Program Description Document,		
		Pages 2-137 to 2-152		
	в.	With Respect to FIPS PUB 38,	•	12
		Program Maintenance Manual,		
		Pages 45-47		
	c.	With Respect to MIL-STD 1679 (Navy),	•	14
		Configuration Management,		
		Pages 23-24		
III.	отн	ER COMMENTS	•	16
	A.	Functional Description, on Pages 3-1 to 3-3	•	16
	в.	Hierarchical Structure Diagrams	•	16
	ç.	Flowcharts		18
	D.	Interpretation of Hierarchical Structure Diagrams		18
	E.	Inter-Module Message Tables		21
	F.	Configurations		21
	G.	Patch Listings		21

	Page	No.
H. Audit Comments		21
REFERENCES		38
DISCLAIMER		39
DISTRIBUTION LIST		40

LIST OF FIGURES

	Page	No.
FIGURE 4.2 CT Hierarchical Structure (1 of 5)	,	22
FIGURE 4.2 CT Hierarchical Structure (2 of 5)		23
FIGURE 4.2 CT Hierarchical Structure (3 of 5)		24
FIGURE 4.2 CT Hierarchical Structure (4 of 5)		25
FIGURE 4.2 CT Hierarchical Structure (5 of 5)		26
FIGURE 4.3 CT Flowcharts (1 of 25)		27
FIGURE 4.3 CT Flowcharts (2 of 25)		28
FIGURE 4.3 CT Flowcharts (3 of 25)		29
FIGURE 4.3 CT Flowcharts (4 of 25)		30
CMS-2 ASSEMBLER		31
REVISED FIGURE 4.2 CT Hierarchical Structure (2 of 5)		36
REVISED FIGURE 4.2 CT Hierarchical Structure (5 of 5)		37

I. INTRODUCTION

A. Purpose

Trident CCSMA has requested the Naval Postgraduate School (NPS) to evaluate the "Maintainability Enhancement for TCP/TSP Revision 6.0 Update .20" documents, subsequently referred to as 6.0/.20, with respect to its usability for maintaining Trident Command and Control System software.

B. Approach

It is understood that one of the governing documents for the production and use of Trident software is "Department of the Navy Tactical Digital Systems Documentation Standards," SECNAVINST 3560.1, 8 August 1974. Therefore, it was deemed appropriate to use this standard as one means of evaluating the subject documents. It was felt that, as a minimum, documentation used on the Trident project should meet the applicable sections of this standard. However, recognizing that this standard was issued many years ago and that the field of software engineering has evolved in the interim, additional criteria which reflect more modern software design and maintenance techniques were used in the evaluation.

The part of 3560.1 which appears to be most applicable to maintenance is the Program Description Document, pages 2-137 to 2-152. As stated in this document, its purpose, in part, is the following: "As a detailed compendium of the subprogram structure, the Program Description document

will serve as the essential instrument for subsequent use by operational, maintenance, and contractor personnel diagnosing troubles, making adaption changes, designing and implementing modifications to the system, and introducing or adding new subprogram functions to the completed program" (underlining added by the author).

Another means of evaluation was with respect to the publication
"Guidelines for Documentation of Computer Programs and Automated Data
Systems," National Bureau of Standards, Federal Information Processing
Standards Publication 38 (FIPS PUB 38), February 15, 1976. As stated
in FIPS PUB 38, its purpose is the following: "These guidelines provide a basis for determining the content and extent of documentation for
computer programs and automated data systems. Software development
phases and related document types are identified, several examples of
documentation options are given, and content guidelines for ten document
types are provided." Although, officially, this guideline is not
applicable to Trident software because it was written to apply to ADP
systems under the provisions of Public Law 89-306 (Brooks Bill), which
excluded embedded computer systems, it is of technical interest because
it is one of the few Federal Government software guidelines which
covers program maintenance.

As stated in FIPS PUB 38, "The purpose of the Program Maintenance Manual is to provide the maintenance programmer with the information necessary to understand the programs, their operating environment, and their maintenance procedures." The Program Maintenance Manual is described on pages 45-47 of FIPS PUB 38.

It was also considered important to examine 6.0/.20 with respect to the applicable sections of MIL-STD 1679 (Navy), 1 December 1978,

the Navy's Military Standard for Weapon System Software Development. The applicable section of 1679 is primarily 5.11 Configuration Management, pages 23-24.

C. Scope

In order to ensure good software maintainability, it is necessary to use sound programming methodology and procedures, as well as provide good documentation. It is difficult to evaluate the quality of documentation and not also consider the quality of the product that has been documented, because good documentation of non-structured programs which contain machine language code, although of some benefit, will not result in good software maintainability, nor will good documentation of highly patched programs allow software to be easily maintained. In other words, if programs are inherently difficult to change and understand and may not have been designed with maintainability in mind, documentation may only make a marginal contribution to the improvement of maintainability. Thus, this project poses a dilemma because we have been asked to review and evaluate documentation for programs which are non-structured, contain significant amounts of machine language code, and are highly patched. It is understandable that this is the case, since the programs were designed prior to the availability of a mature structured programming methodology and high level languages for tactical system software development. In addition, although machine language patching is generally considered to be undesirable, for certain administrative and contractual reasons it is a prevalent practice in Navy embedded computer software development. The argument can be made that, because of these practices, good documentation is even more important in this environment than it would be in those situations where the use of structured programming and high level languages provide a degree of self-documentation. Accordingly, the scope of this paper will be limited to evaluating the adequacy of 6.0/.20 for maintaining the TCP/TSP software, ignoring what is perhaps the more fundamental maintenance issue of the adequacy of the underlying software.

A major assumption of this study which affects its scope is that the 6.0/.20 documentation is to be evaluated independently of the program listings. It is noted that listings are not included in the version of 6.0/.20 dated 29 September 1979, although these were included in a prior version (undated). Quoting from Volume 1 of the version dated 29 September 1979, "The primary goal is to improve this software's maintainability by making the programs and their patches understandable and visible in a single simplified form," (underlining added by the author). The implication which has been derived based on the above statement and the fact that the listings are not included in the latest version, is that 6.0/.20 is to be used for maintenance purposes primarily on a stand-alone basis with listings utilized as a secondary source of information. This interpretation is critical with respect to some of the results obtained in this study, because certain deficiencies in 6.0/.20, which are noted later in this report, regarding such items as data design, tables and indexes, are not addressed by 6.0/.20 but are covered in the listings. If it was the intent to use the listings with 6.0/.20 in a coordinated fashion, it would be helpful to provide a detailed cross-referencing between the two. A method for accomplishing this cross-referencing is suggested

in a later section. The scope of this report is limited to considering 6.0/.20 as an independent tool for maintenance which does not rely extensively on the use of program listings. However, since the flowcharts are based on the program logic, as expressed in the listings, it was necessary to make extensive reference to the listings in this report in order to understand and evaluate 6.0/.20. In fact, a result of this analysis was the conclusion that the two mediums should be used as an integrated documentation package and not in isolation.

II. EVALUATION OF 6.0/.20

A. With Respect to SECNAVINST 3560.1, Program Description Document, Pages 2-137 to 2-152.

The following 3560.1 pages and sections are covered by 6.0/.20:

Page	Section	<u>Title</u>
2-141	1.	Scope
2-141	2.	Applicable Documents
2-142	3	Requirements
2-142	3.1	Subprogram Detailed Description
2-143	3.2	Subprogram Flow Diagrams
2-148	3.6	Conditions for Initiation
2-149	3.8	Interface Description

The 3560.1 pages and sections which apparently are not covered by 6.0/.20 are identified below. It is possible that these sections are not applicable to certain volumes of 6.0/.20. However, the named missing sections were not found in any of the 6.0/.20 volumes for which copies were provided to NPS, so it is assumed that it was not intended to include these sections in 6.0/.20. A brief description of the intended contents of the missing sections as specified by 3560.1 is given:

Page	Section	<u>Title</u>	Contents
2-144	3.3	Subprogram Data Design	General summary description of the subprogram data base.
2-144	3.3.1	Tables	Detailed description of each table used in the subprogram data base: a. Table name. b. Purpose and type. c. Size and indexing procedure. d. Structure and bit layout.

2-145	3.3.2	Variables	Detailed description of each variable used in the subprogram data base: a. Variable name. b. Purpose. c. Structure and bit layout.
2-145	3.3.3	Flags	Detailed description of each flag used in the subprogram data base: a. Flag name. b. Purpose and status. c. Structure and bit layout.
2-145	3.3.4	Indexes	Technical description of each index used in the subprogram data base: a. Index name. b. Purpose.
2-146	3.3.5	Common Data Base Reference	Complete list of all references to local and common data base items and the location of each reference.
2-146	3.4	Input/Output Formats	Brief description and graphic (sample) representation of each input and output message, card format, tape format, etc. processed by the subprogram.
2-148	3.7	Subprogram Limitations	Summary of any known or anticipated limitations of the subprogram.
2-149	4.	Quality Assurance Provisions	Reference to all applicable test plans and procedures that have been used for verification of the subprogram. (6.0/.20 should reference the Trident Test Specification Requirements and Test Procedures which are described in Refs. 1 and 2.)

NOTE: It was not possible to determine whether Section 3.5 Required System Library Subroutines was covered by 6.0/.20 because it was not known whether library subroutines were used.

B. With Respect to FIPS PUB 38, Program Maintenance Manual, Pages 45-47

The following Program Maintenance Manual sections are covered by 6.0/.20:

Section	Title
1.	General Information
1.1	Summary
1.2	Environment
1.3	References
2.	Program Descriptions
2.1	Program Identification
2.1.1	Problem and Solution Method
2.1.2	Input (description of)
2.1.3	Processing (logic, linkages, error handling)
2.1.4	Output (description of)
2.1.5	Interfaces
2.1.7	Run Description
3.	Operating Environment
3.2	Support Software
3.2.1	Operating System
3.2.2	Compiler, Assembler

The Program Maintenance Manual sections which apparently are not covered by 6.0/.20 are identified below. The caveats that were stated relative to 3560.1 also apply to this section.

Section	Title	Contents
2.1.2	Input	Layout, medium, codes, units of measurement, format, range of values or reference to a data element dictionary.
2.1.3	Processing	Variables, constants, restrictions, switches, flags.
2.1.4	Output	Layout, medium.
2.1.6	Tables	Identification, content, location, structure, purpose.
3.1	Hardware	Equipment required for operation of system and for each program.
3.3	Data Base	Description of data bases used or reference to a data element dictionary (codes, units of measurement, format, range of values).
4.	Maintenance Proced	ures
4.1	Programming Conventions	Identification and descriptions.
4.2	Verification Procedures	Description of procedures to check the performance of programs, in general and following modification. Reference to test data and testing procedures. (6.0/.20 should reference the Trident Test Specifi- cation Requirements and Test Pro- cedures which are described in Refs. 1 and 2).
4.3	Error Correction Procedures	Description of error conditions, sources and procedures for correc- tion. (6.0/.20 should reference the Trident CCS Problem Reporting and Modification Systems which are described in Refs. 1 and 2.)
4.4	Special Maintenance Procedures	Description of special procedures which change with time or conditions (e.g., change of parameters, algorithms).
4.5	Listings and Flowcharts	Information about how to obtain copies of listings and flowcharts.

NOTE: It is possible that Section 3.3 Data Base is not applicable to any of the programs documented by 6.0/.20.

C. With Respect to MIL-STD 1679 (Navy), Configuration Management,

Pages 23-24

The following configuration management sections of 1679 are covered by 6.0/.20:

Section Title 5.11 Configuration Management 5.11a Positive identification of all program components 5.11.1 Configuration Identification 5.11.1.1 Baselines 5.11.1.2 Documentation Identification 5.11.1.2 Component b. Purpose

- D. Purpose
- c. Baseline
- d. Serial, edition and change status

The sections which apparently are not covered by 6.0/.20 are identified below. The caveats that were stated relative to 3560.1 also apply to this section.

Section	Title
5.11b	Treatment of proposed changes to components under configuration control.
5.11c	Implementation of approved changes and dissemination of corrected documentation and program changes.
5.11d	Recording of status of all proposed changes.
5.11e	Verification of change control, identification and status account of documentation and program materials.

5.11.2	Configuration Control	Procedures for formal control of all documents, program materials and support library shall be established.
5.11.2.1	Software Changes	Proposed changes to software which is under configuration control shall be submitted to the appropriate software configuration control boards.
5.11.2.2	Documentation Changes	Procedures for control- ling preparation and dissemination of changes to documentation shall be developed.
5.11.2.3	Software Configuration Control Boards	Each baseline plus approved changes from those baselines shall be under the formal control of a responsible board.
5.11.3	Configuration Status Accounting	Procedures to enable the generation of periodic status reports on all components under configuration management shall be established.

With respect to the above sections, 6.0/.20 should reference the Trident CCS Problem Reporting and Modification Systems and the Configuration Management System which are described in Refs. 1 and 2.

III. OTHER COMMENTS

The following comments pertain to 6.0/.20 Volume 2, using it as an example.

A. Functional Description, on Pages 3-1 to 3-3

- 1. The discussion would be more meaningful if it were keyed to the hierarchical structure diagrams and to the flowcharts. For example, definitions and descriptions of pertinent interrupts should be provided, including important symbolic addresses which are utilized. This information and the interrupt numbers should be related to the diagrams.
- 2. Sub-headings for the various sections, such as "Interrupt Handling," would make the text more readable.
- 3. Some typos were observed which affect understandability. For example, the fifth line in the second paragraph on page 3-3.
- 4. Although this comment does not concern quality of documentation, it was noted on page 3-2 that the control memory test for all zeros and all ones should be preceded by setting the relevant portions of main memory to non-zero and non-one data, respectively, prior to the transfer of control memory to main memory.

B. Hierarchical Structure Diagrams

1. Hierarchical structure diagrams and flowchart symbols should be defined at the beginning of each volume. It is not clear that these diagrams strictly adhere to ANSI standards (see Reference 3).

- 2. A consistent hierarchical structure box numbering system should be utilized which would indicate at a glance two important pieces of information: the function (e.g., "Periodic Entry") to which the routine belongs, and the level of the routine within the function. This scheme is shown on the accompanying hierarchical structure diagrams, which were reproduced from Volume 2 (pages 4-4 to 4-8). The left digit is function number, the middle digit is level number and the right digit is routine number for a given level and function. Level numbers start at "1" and increase from top to bottom; routine numbers start at "1" and increase from left to right. These numbers should be referenced to the pertinent flowcharts, as shown on the accompanying diagrams (pages 4-9 to 4-12 of Volume 2). As a means of tying together hierarchical structure diagrams, flowcharts and listings, the identification numbers could be appended to the listings as shown on the reproduced CMS-2 Assembler listing (page 6 of listing), which is attached. Two columns are utilized: one is the "At" column corresponding to lines with labels; the other is the "To" column corresponding to lines with transfer of control. Perhaps these identifiers could be punched and printed in formatted columns as part of the "Comments" field. A further help would be to sort source statements by the "At" column and to indent based on the middle digit. This would provided a structured listing of an entire function in contiguous locations.
- 3. Although it is not a fault of the flowcharting process, it was observed that there is a similarity of labels (e.g., CTPRE and CTPER). This could lead to error in software maintenance.

C. Flowcharts

- 1. The entry to a flowchart page should be annotated with the flow-chart page numbers which are associated with the source(s) of the transfer of control and the exit(s) from a flowchart page should indicate the page number(s) which are associated with the destination(s) of the transfer of control. This is shown on the attached pages 4-9 to 4-12 of Yolume 2.
- 2. There is no loop back to CTPERI on page 4-9 of the flowcharts, as indicated by the JBNZ instruction at line 223 on page 6 of the listing. Instead the box at the bottom of page 4-9 reads: "Repeat Data Pattern Test Using 'IWC' Control Word." Similarly there is no loop back to CTPER2 on page 4-10 nor loop back to CTPER3 on page 4-11, as shown by line 230 and 238, respectively, on the listing. This method of presentation seems to mask an important characteristic of the program logic.
- 3. There seem to be discrepancies between flowcharts and listings. For example, the second box from the bottom of page 4-11 figure 4.3 refers to IWC. Page 6, lines 243 and 244 refer to ICW. The box in the flowchart also refers to "Set Up Class IV," while line 243 on the listing refers to Class II.

D. Interpretation of Hierarchical Structure Diagrams

1. Using Volume 2 as an example, it appears that the hierarchical structure diagrams are not totally accurate in portraying program logic. For example, the following discrepancies were noted between hierarchical structure and the listings:

- a. With respect to page 4-5, figure 4.2, CTPER is shown superior to all other routines on this chart, yet an analysis of the listing reveals that CTPER only happens to be the first label in this series of code and its only paths to other labels are to CTPERI and CTPERROR. The latter reference brings to light another discrepancy. CTPER does have a conditional branch to CTPERROR in the listing (line 219), but according to figure 4.2, there is no path between these routines. With respect to figure 4.2, the listings indicate the following access paths among routines:
 - CTPER accesses CTPER1 and CTPERROR.
 - CTPERL accesses CTPER2 and CTPERROR.
 - CTPER2 accesses CTPER3 and CTPERROR.
 - CTPER3 accesses CTRTN and CTPERROR.

Thus, a more accurate picture of this logic is shown in the diagram labeled "Revised Figure 4.2 CT Hierarchical Structure (2 of 5)." It should be noted that in this diagram the horizontal lines indicate paths between adjacent code segments that are in the same module and vertical lines indicate paths involving transfer of control. Also, the arrows, from left to right and from top to bottom, indicate the general direction of control flow. In large measure the "routines" which have been shown as hierarchical structures boxes in Volume 2 are simply labels in a segment of code. This has been pointed out in Volume 2 on page 4-3. The difficulty in constructing the hierarchical structure from program listings is that by definition, the diagrams are supposed to indicate hierarchy, i.e., superior-subordinate relationships, and programs designed using a top-down approach. Since the

programs were not written this way, the imposition of a hierarchical structure on a coding format that is inherently non-structured will lead to incompatibilities between diagrams and listings, unless great care is exercised in performing the translation.

- b. Pages 4-7 and 4-8, figure 4.2, show CTKLAS2 as having access to CTKLASY. The listing indicates that this actually occurs via CTKLIPI (lines 314 and 342), which is not listed as a routine in figure 4.1, page 4-2 of volume 2. CTKLIPI also has a path to CTARITH via CTKL2XIT at line 349. Page 4-8 also shows no path between CTKAS2I and CTKLASY*. However, the listing shows this path to exist. This condition was verified by consulting the CMS-2 Assembler List Cross Reference Table. One of these references to CTKLASY occurs from the same routine.
- Pages 4-7 and 4-8 show no path between CTKLAS2 and CTKLAS2Z. However, line 335 on the listing shows that this label is contained within routine CTKLAS2.
- Page 4-8 shows no path between CTKLASY and CTKLAS2J. A check of the List Cross Reference Table revealed that this path does exist; this reference to CTKLAS2J occurs at line 430. However, this path is used only when a 4 stop condition does not exist.
- Taking the above difference into account, page 4-8 has been redrawn and is labeled as "Revised Figure 4.2 CT Hierarchical Structure (5 of 5)." Again, the procedure was to use horizontal arrows (going into side of box) to indicate adjacent code segment relationships (e.g., between CTKLAS2 and CTKLAS2Z and between CTKLAS2I and CTKLAS2J) and vertical arrows (going into top of box) to show transfer of control.

^{*}At least it is not unambiguous as to whether there is a path between CTKLAS2 and CTKLASY or between CTKLAS2I adn CTKLASY, or both.

- Note: The revised hierarchical structure diagrams would obviously have different numbers for some boxes than those used in Section B.2. The latter was based on the given hierarchical structure diagrams as shown in Volume 2.
- c. It was not clear in what sense lines with arrows and those without arrows were used in the hierarchical structure diagrams of Volume 2. If the use of arrows was to show transfer of control and the absence of arrows to tie together routines of the same module, the method would be inconsistent because there are no arrows on the lines which connect CTKLAS2 to CTKLAS2(A-I) in figure 4.2 of Volume 2.

E. Inter-Module Message Tables

These tables, such as the one on page 4-34, figure 4.4, Volume 2, should indicate the page number of the flowchart of the referenced procedure (routine).

F. Configurations

The hardware and configuration to which 6.0/.20 applies should be defined in each volume.

G. Patch Listings

Patch listings in Volume 1 should have column headings.

H. Audit Comments

Although we do not agree with the comment on page A-1. Volume 2 that, ". . . the module is readily understandable even though it is non-modular," we do feel that this is a valuable part of maintenance documentation. Perhaps this section could be expanded.




FIGURE 4.2 CT Hierarchical Structure (1 of 5)

Page 4-4

PERIODIC ENTRY

FIGURE 4.2 CT Hierarchical Structure (2 of 5) Page 4-5

CLASS II INTERUPT HANDLER

PERIODIC ERROR

4-STOP

CTPERROR 2.3.

CTKLAS2 2.3.




FIGURE 4.2 CT Hierarchical Structure (3 of 5) Page 4-6


CLASS II INTERRUPT ENTRY

FIGURE 4.2 CT Hierarchical Structure (4 of 5) Page 4-7

2.5.1

CTKLAS22

SET EXPECTED ISC AND RETURN TO TASK STATE







FIGURE 4.3 CT Flowcharts (1 of 25)
Page 4-9





FIGUPE 4.3 CT Flowcharts (2 of 25)
Page 4-10




FIGURE 4.3 CT Flowcharts (3 of 25) Page 4-11






FIGURE 4.3 CT Flowcharts (4 of 25). Page 4-12


: AIS	1, t T. 18	0	;	<u></u>	= =	<u> </u>	- <u>;</u>-	3	-7		<u> </u>	.	I	2:	13	ĸ	•	×. 2.		-	2.2	7.7.6			<u> </u>		2.4.0	000	Į.,	: 1	Ĭ.F.	7]	F	1	7.3.1	2.2.3	٠ <u>٠</u> .			<i>-</i> _	[7]	T	₹_₹	2	73	E4		U		=	٤.	1	<u>: •</u>	•	
٠	Flow chart	+4		598	5*0	1.5	~			740			~	,	0.7.1.1				100 2.2.1				•	111 2. 2.6	_			n •			2.2.3		121					136	127	126	129	130	131	132	(*)	+F	135	97	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		110 0 24		•		
r A G.	SEMPEMLE		CTM1603/1	CIMICORE	01110040	[400] [41.7	£15642	c 15842	£ 158.2	74071W17	CINIULGO	Claineal	Cfillor92	11817	CIRCOS		CIMIUSI	CIMIUIUS	C1M1:108	CINICIU	CIMICIUR	Clivicion	CTMICITO	C1410111	10143					7 101213		CIMIU120	C1410121	C1410122	CTM10123	CTM10124	CINIO	C1416126		-	C11111129	Cluini30	1610131	C141.3132	Cfalul 7	telalula telalula		96101017							
	Connents		. CLEAN ERRUN FLAG	. 1.21.1	. DELETE FEXTODIC	. DELETE DEFENRED	•		•	· + X - 1	ARESAME ENTRY FLAG	. tyAblt PRINELEGED INST.	4 STOP		INDIRECT ADDRECSING TES	C-SullCH FAU Flac S II	CHECK DEFENSED ENG		. CHECK READ CLASS	. 15 11 CUMMECT	01 GC 10	10111	. CHECK STUHE CLASS	•			1 CACCA 11		CLEAR MASK	TEST KNOTACE CLACK			- LANCK IT		15 17 Condect	TAN BUTH		. GET EAEL STATE CONTRCL	Ξ		· (SAVE CLASS II 1CW)	- CE	E EXEC SI	. Sti UF EALL SI		. PREPARE TO GO TO TASK		. CLEAR INTERNET COUNTER	•				-		
18SFOMLER	UPERALL		BUICTERFLAGING	SEENIT	SSDELPER	58061166	AG. CTERHJGE. NU. B 511	A1.4	580115	SSERIT		SAPPLY	4.07.5100	ACTION DESCRIPTION			•	CIPERROR.	ABI . CTROIDALING. LT	AG.CTC1.K3.B7	CIPERROR	by CTELED		AU.CT25PAT.K3.R7	AU C T 10RVI. K3. 67	AUICTALIKA187	AUT. (22.18.3.18.)	A V COLOR			A() (+ 2CPAT . K 3. H 2	A7.ecf10401.87	C 0 - 1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	AU.CTC2.K3:67	CTPERSON	H7 (C13/ P3)	_		P70,CTASR1	DICTINIERS	DAY, CTINIEN!	044.CT(NT# 21	CZ1,CTINTEHZ	11.2 1 . A IJ	0.21,40	CIND CTASH2		hu.Crc.ign11.44		VOICTCHDE IN 3	5	1	DITIC does not	available to production	שלים שלים שלים שלים שלים שלים שלים שלים
CH5-2 - 15.5	ማር ተወስደ		3	S	SX	×S	۲,	۲,	8 %	:S #	70	· **	, s			1	,	3116	۲,	Ų	JNE	711gf	LG	۲,	₹.	, ۲	ة و	101	7 4 7	ž (1		44.			JAK	18.42	PRIVILEGER	SX	2	158	105	<u>.</u>	7.5	H2(1	- T	: ر	ر ا	dS.	.	Ç :	- 3	-		available	oit fully leg
	LABEL				CTOIS						CIMERR	CTHERMI	CTASTOR						CTPERI					CTPER2								, , , ,					•														2 2 3			<u></u>	
CTA	ACUR FARB ST		0 0 6 6	- -	- - -	nevert of 0 0 0 000110		0 0 0 1 0 1	0000000	*00000 U H O D 25	20 4 1 0 0 000100	UZ 10 0 0 000425	53 4 3 0 6 0 000051		touther a a A as example.		1000153 42 42 0 0 0 000521	0 1 0 64	524000 1 2 C n nt 550063	0 1 6 0	0 - 1 0	307	9	10 0 3 7 0	C 0 +2				26 / 1 0 U D CCOUG	20 7 20 20 20 20 20 20 20 20 20 20 20 20 20				44 6 3 7 6	0 0 1 0 15 9	52 7 1 9 6 0 00007		Jul 100 67 0 0 8 1 1.00425	54 71' () f' n(1051	: 0 :0	15000 0 0 44 75	25 44 0 U 01051	9 12 25	6.0 23 U	0 17 19		0 0 75 55 01	5 5 6 0 6 7 TE			14 57 6 5 5 5				
	10 6 11 AC		16110	26100	66160	# 6 Tu:-	26.1.10	111.196	261 111	45 T	6.11	11:20	11261	200			11:21 P	617.14	1,1220	122111	(1)222	→t-1223	11:234	6.1225	511225	1727	377	476.4	100 mm	212	[1, 2, 13]		111.2 15.	11.236	71,237	9621.4		11.240	162.0	21.241	Jui 243		. 11.2.15	9 % 2 (1)	1.0247	111249	A	0.125.0	157.10	757.11					

FAGE 7	sk autikki	24101417	CIMIUIAS	C1#10144	C1210142	C[#13146	C#101917			C1410151	C1#10152	C1810154	CINICISS	95101210	C[31:158	CTM10157	CIMICIÓN	65111117	79101017			CIMIUIOS	CIMIUI65	C1410168	C1010167	0.101813	64101413	7/10/015	*/ 10 TN 10	CIUINIS	CTM10176	CTM10175	CINIU178	C1410179	CT410180	CIMIUIBI	C1410182	7810187 T		6210171	1 646447	C1:11:11:0	Cintulay	Clainted	56101H13	C1410143
	CORNEATS																																			GENERATE FLOAIING		_	4EAC 1 88	THE RESERVE OF THE PERSON OF T	: :	. 105Taucijos fyklali		11117 0	AII FO	S Tr. JASK REGISTING
	COR	•	•	•	•	•	•	•	• '	• •	. -	•	•	•	• •	•	•	•	•	•		•	•	•	•	•	•		• •	-	•	•	-	• •	•	•	•		1 1 1 A 1 4	0.44.	1		:-		•	2 LH40h3
*SSEPALLA	UPERANT	~	=	*	*	020	040	0/0	500	0.00	0/0	11.20		0,90	070)	. 04	,	020		200	070	•	, AO		c								6	5	AULTOUFS	AU CTOILES	·	AU.CTUPLIABILSCTINANA	AU-CTOP2, KA-SC 1 LAND	10101111111111111111111111111111111111	-	F*1 SCITKANS		CIUPA	offine fug CLASS 2 throbs (770,crask)
CH5-2 45	UP CODE	2	ĭ	75.5E	٦ <u>\$</u> ر	רכו	רכז	5.		200	108	HSCT	⊃ ₹	H D S H	1.52	- ON I	1358	ONE	HLCT	0 N T	##C1	H C 4	ONH	HLCI	O M	£ 75 E	3 K	- : L :	141	INC	HALT	2 T	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	_	AEI	0 F	V L	• ,		.	, -	, 2	ר ג'	ار د	7	LASZ LCI
CTA	HAL ADDR F A K B I SY LABEL	* 3	23 97 4 5 0 0	0002455121	2 53 4 3 0 0	1 54 50 0 U	124 54 60 0 0	25 54 70 0 0	20 20 1	0 0 05 95 05	0 0 0/ 95 16	132 40 20	2 74 U 3	133 611 60 0 U		E (1 % 2 % T)	135 60 00 0	35 74 U 3	136 61 20 0 0	34 74 0		3	140 74 0 3	un 19 141	1 74 0 3	0 0 1/ 2h1	142 74 0 3 0	43 77 6 4	144 77 0 5 0	144 74 6 3 5	9 11 11 541	145 74 0 3	9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	147 07	159 07 0 1 0 0	00005015	152 06 U U	153 90+0-0+00000	154 10 U 3 D U 4 UN154	= :	136 24 U 3 G C J (0136)		161 53 0 3 0 0 0 5 60142	62 20 u n u n u uithaun	3 53 U 3 U Q U QUUIK3 ETU	258733 Office of the Ashabiton
	. L a1	746.00	140.257	6521	45860	05230	14250	262	0.77.3	5 4 6 G G	11.256	£	111.258	84200	0/2un	7/2/11	•	1111274	5/707	0:1276	0.1277	97700	0.1240	19291	T	0.1703	4420n	UF 285	(10.29.7	17.7 FB	0.1297	11.230	16751	111293	11-294	111:295	1:11.236	154.29.7	662111	652.111	1000	10130	101393	411.3114	506.50	701 July 1017


3118	591011	J	ć	=			H2C 1	1.46.34	. CHECK STATUS COPP.	c Inferse
90801	991016	3		3			3	7.00		CIPIUIYS
	7910m	7 1	- ·	o :	0 60054		- e	A1.6C.1C.0C.1A.F.3	STATE OF STA	/A101817
00312		•				•	•			
-							and daladde	(Ory-11 dar - 222 dad	いいい いっぱん かんいいかい かいかい アイ・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	7.4.7
\$ 1 TO 10 TO	121000	3	- 7	2	0 0 000221	3	LMI. PERSONE	CTKL [VI)	TALL CANAL CONTRACTOR OF CONTRACTOR CONTRACT	1 a
417 TH						•				:
	5710111	7	-		0 000034		J	P1.28	. ALL PRIVILEGED INSTRUCTIONS	0117 CINIO C:: N
91600	11000	3	- -		0 0 000227		4	CTSLASZA	•	10771417
\$15mm	F/1000	÷	=	⇒	3		J,	41.29	. Inter Province Polat	707-11017
02500	57 Into	·	- ·				4,	CIKLISZU		
17600	~ 1	7			0 000034		^ي ن		. Intel literat incline	#0738#J
UH 322	2.1500	7 :	- : 				ų,	11 27		3 :
2000	107000	F					ية ر		THE OFFICE AND AFTER	
	202000	7			. 3		5 .	AL 32		97771817
11. 12.5	107000						4	CINESSE		5
• •	400000	* *	· -		3		٠,٠	A 1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	TRIED UPPERANCE LAIL	C[4162]U
• ^	10000	·	. –				i i	CTKLAS26		5
(11:329	000000	*	3				·	A1 . 34	INTED THE HASTAUCTION EALLOIL	
05501	000207	2	_	_	_		4	CIKLAS2G		
16600	0.00210	Ŧ	<u> </u>				J	A1,35	INIEG INSTRUCTION LINIT	CIMINZIA
06332	01:0211	Ą,	_	9			4	CIKLAS2H	•	C1410215
110333	212000	*		3			u '	A1:34	. INIEU CP HOUSTON CLUCA	C[8]::210
11:334	900213	3			0 000252		-	CTKLASZI		
1335	12000		٠.	⊃ ⊃		CTKLASZE	`	AU.C CCODE, N.3	PANE NEAT EXPECTED STATUS	
98660	7	= :	٠ '	-			J.F.	D4.740	TEGET LIBORT	1771 LI
00337	41200C		=	ə ⁻	loonon c				•	07751111
0 0			. •	•						
10.234	ロラアのいい		ت. ت	- -		•	<u> </u>		1811 1434 11 1	77701uli
0 + 7 (1)						•	aradade,			3
41.134.2	2000	-	-	=	1. U.10.33c	CTKLIFT	7N1	AU A THE ASY		
	ь					797	ITTHATE IN	1 -t CE TIED FHUM DISC.	LEGITINATE IN A CELVED FROM DIMEN PROLESSON DURING THIS ILST	. 2
*****						•	GENENATE	NEGENERALE THE 1PT TO PREVENT LOSS		. 1
345	1111. 755	2	د د	= ວ	1 000425		,	SAAPLIV	. ALLOS PRIN INSTR	
クチベンコ	900223	0.7	٥,	ɔ ˈ				Secreta	. CEL IMIS PROCESSIA NUIBER	
16347	100224	- :	_ `	•			HL(T	31111	Y TO THE TOTAL TOT	
9 7 9	91000	35	v .	- -			Ę.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CONGRETAL ACTUAL PARTS OF THE P	
44600	84.700	,				90000	3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	1 22 34 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3		. :
10.00										_
0.352 0.352	0.09227	<u>-</u>			1000000	CIKLASZA	۲.	1.01	STORY CALLS CALLS AND THE CALLS OF THE CALLS	0. 4.60223
5	1)00230	5	-	0				CTKL S72		
	162000	2				CIKLASZU		10,2	I TEREBAL LASTINGTION	CIPIUNE
655,00		_						1.TKL1522	•	CIM10226
10.356	-	=	= =			CIKLAS24	4 1	40.0	. UPERANJ MEND	C1810247
1367	*6200	~		<u> </u>	1 6 000214		7	C1843522	-	cln11.40
9000	2	<u>a</u> :	۔ د د	÷ :		CTKLAS2D	۲. د	110.01	4 Breakto unibe	Cluster
	¥	•		=	2020 0		-	C1KL 45.22	•	2642111

	CTA	Z-5H7	155E1146EP		r. Abk. 4
0.00	S I B W B I SY	LABEL OP COC	e upfika.n	Cunntals	Things' is
Sec. 100	0 0 0	CTKLAS2E LA	40.til 2	. OPERAND LINIT	16/91017
14600	0000		CTKLA522	•	CE41153
110.3 4.2	2 7 0 0 01 1	CIKLAS2F LA	510.04	I INSTRUCTION EAFCOTE	C1410233
1.0343	42 53 13 11 10		CTKLAS22	•	CIM10234
11.354	J 6 0 24 59 64	CTKLAS26 LC1	647 CIPURPAI	. MESTONE SI TO PISTONE	C1#10235
5480	0 10 10 10 11	5 ·	AC. E. A.	. Italkorilor clair	962(1417)
946 171	45 53 0 3 0 1 		CIRLAS?		/ F Z 3 C 1 C 3 C 7 C 7 C 7 C 7 C 7 C 7 C 7 C 7 C 7
() B () .	10 0 14 CS 94	CIKLASZM LYI	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	THE STANK OF THE STANK	500 TO 13
6 7 F 11 1	247 10 0 0 0 0	٠. د	Autul7	THE MONTHUM CLUCK	7570100
7 11 3 A 4			פוחיכוכרע	. LOAD OF BOAT OF CLUCK	
01.370	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		C1KLAS22		0FX0TE13
70.00	0 n n / 07 ZS	CIKLASZI LU	001012	+ SAVE EARL ARGISTERS	177014
r. 1.372	23 20 1 0 0 6	9 ;	21.6		11121111
C-0373		9 8	50 CTERFLAGIKA	· CITAN TLAG	714701417
1:0374	0 0 9 2 70 50	L (7.6	•	2 L 2 O U 1 O
011375	0 7 1 10 75 95	158	AU, CTREGSTK, BI		C1410243
11:376	0001020219	9	010178	. LUAD WITH ZERDES ESSI	CTH10244
00377	7 7 6 0 0	Q	•		54201H17
111378	0 10 0 00 55 15	וכו	AU,CTOHPAT	•	C11111246
97600	62 20 7 U D P	9	B7 . O . 7	•	1155411
00340	63 07 7 6 0 0	<u>a</u>	•	•	1165211
19696	4 55 11 0 11 0	וטו	O11,CTOMPAT	•	11652111
110.142	15 20 7 0 U D	9,	97+410u.	. STURE ANAT	C1410241
10383	96 20 1 0 0 0	3	0.10	•	126201413
110 34 4	0 0 9 7 70 7	2	7.1	•	61416248
ve.385	. 57 09 1 0 3	15\$	AUICIENPSIKIUI	•	C1410249
111346	1 20 7 0 10	3	97,0100	. CHECK THEM	05201613
10347	3 3 0 3 0 0	95	BO, CTENPSTK+U10, A3	•	** * * * * * * * * * * * * * * * * * * *
88EDA .	30 1 U C C	3. °	2116	-	CTM102501
. 111339	00 9 0 40 1	~	1. 0	•	CTH10251
06000	75 10 U 3 1 0 G	5			C1810252
167.1	2 2 2 1 0 0	Zhār	H7 66 TR L 45 Y		C1#10253
6,392	7 20 7 0 0 0	9		. CHECK WITH ONES	CTM10254
110373	30 07 7 6 3 0	- - - -		-	C1n10255
. LB394	101 55 UU 0 U 0	J :	A0. CT014ES		CIM10256
00375	302 20 7 0 0 0		87.010a	. TO TEMPORARY STOWAGE	CIN10257
966.1.	303 20 1 0 C C		0.18	•	1/520/010
1.0347	0 0 0 / /0 4	ا الا	107	•	9670111
9/ Cur.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		AU-CTERPSIN-BI		A670[UI]
66E(1)	1306 20 / 15 0 1	9 :	00101	+ CHECK 1357	39701H13
U(1+1)-1	07 20 1 0 0 0		3.1	•	199201117
	0 0 4 / 70 01	F 4	111	•	
2116311		¥ 4 .	AU.C.1 F. 1 F. S. T. V. J. IV.	•	C1210202
Cirtur	2 0 2 0 2 1 2 1	4 H	AU 1 C1 C0 11 5 1 1 1 K 3	•	F9201413
			AUG.TRIAST		
	1 0 0 1 02 418	CIKLAS2J LB		THESTORE CRESTICE COLLEGES	
90100	1 1 1 1 0 2 518	9 9	87 en j 6a	•	C1316260
1104117	316 07 7 6 11 13	T.	7.1	•	/ 10 1 1 5 9 V
4:+:·	nin317 55 an 1 n nan531	J .	•	•	C15.15266
61.4.9.		PERIOUIC	1. C. S. PASSED		C1010289
0			•		
		. Prprintri	Dr. / Hawellee J.J. J. J	Proprored recent of Property of Lander Anna Control of the Property of Control of Contro	-

	C1 A		135. Z-SNO	734L : 644		F. A. U.
3 3 3	AC ADUR PAKEL SY	LAbel	Jane Ja	UPP KANT	Connegato	314 407 10
10412		CTKL2X11.	e de la de	न निवस्ति के अनुस्ति हो हो हो हो हो है	er ver er e	<u>.</u> .
-	3					
51400					. RESIONS EAST NICESIONS	3/201013
) C		7.0		- ,	1,201,013
A 1 4 7 7 7	0 0 54 55 0			**************************************	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	11.701
51 F (3)	42 00 0			I C I C MF LA L	SEALE RUNCHE SECURE	77/701013
Lu420	- -				と こうしつまっ	C1m102723
111421	1 0 54 55		161 045	OFFICTASKI	+ ASA MAINTAIN LUCKUUI	C14102724
0.6922	,	CT1110	•	A	שיווים	L111112125
624.10	e .		151	147.CT#5TK4	- 6751	
- C+'		1	E (C1410275
576(11)	200332 53 u t u 000332		2 2	CTPLOSOR	a well through the section	CIN10272
62400	1 52 1 0 U		79.1	BICTARITA	•	11.150K211
921.77.	34 07 6 0 0 0		5 ×	114 385	. EALT	01701AL3
111429	35 53 4 3 C O C	CTKLASY	. JSC	4,CI4510P	* 4 STOP On ERROR DETECTION	clulu2/9
05 to 1.	n n n n n n n		7 .	7	TICIDA MENIORE MECETA	י רושונים כ
16400	37 20 4 0 0 7	CIPERRUP	ب دو د است	5 1	ラマブト ロボルー	
Jily 3.2	40 36 06 40 53 0		79 -	ZiCIFRELAG Zinco		118721417
76.50			7		TO THE PRINCE OF STREET	73701017
# T # 13 1	DECISE DECEMBERS CON		10764		of Defendance in the Control of the	1,0704114
46.000	. ,		10 1 7 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2		A CONTRACT CARRY ACTION	. Talu.2823
(6.410)	3.15	CTOEF	0. 0.	ALISCHAL		5050000
86.433	71 2 2 4	<u> </u>	I.A.E.	A2.43	* •	CIPIUSON
46400	0 5 49		HK (A3,32	•	43601413
04400	2 12		¥ E	A2: AB	-	00t01415
700	71 3 2		7 (E	A3.A1	-	/05×141×
24400	3 70 3 2		֝֝֝֝֝֝֝֡֝֝֝֝֡֝֝֝֡֜֝֝֡֜֝֟֝֜֜֜֝	. A	•	CIRICINE
en e	•		HLCI	[] x + p 4	•	4060 July
*****	ے ۔ ٰ۔		HLCT if	A 5 4 A 1	•	oleolul)
C. F.O.			· ·	24.00	_	
0. F. I.				A PER CRIC	-	71651515
8,713	53 0 1		J.N.	2000		*1601017
6.5.7.6.4	71 2 2 4 4		HAI	42.A.		71501-1
05600	10 71 3 2 3 11		HALL	43.4.5	•	C (#11.31c
13000	11 56 2 3 0 0	_	7"F0	AZICTPEPERM	•	(10101)
1011452	12 07 0 1 0	1	٠ ۲	5\$t v []	•	176-11-17
5.54111	n = 10 ff f1	CTOEFERM	2 -	1-1 - C 1 t x t L 2 G	1 Stitute 1 LA.	. Intost.
# G # 11+1	F0:000 0 0 0 0 /0 *1*000		ζ,	7 T T T T T T T T T T T T T T T T T T T	•	2.4.11.1.2
554.4	: :	CTAKLTH	10,	· Links TIC LEST	•	. Perse
404.1.1			. ب	AU C 1 25 P A T	•	112011
\$ \$ 1.00 m	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		<u>.</u>	# 5 1, 1 2 1, P A I	-	
25.			٠,	A46.T25.Pal	-	
A 5				AC. L. 1.251'A I	-	
1961	15 O D E2 (2) (1)		1777	MI + 5.2	•	
- ۵			<u> </u>	AU. AU.	-	
766			1 1	1 7 18 18 7	•	
•					-	•



REVISED FIGURE 4.2 CT HIERARCHICAL STRUCTURE (2 OF 5) REVISED Page 4-5



REVISED FIGURE 4.2 CT HIERARCHICAL STRUCTURE (5 OF 5) REVISED Page 4-8 (1) USED ONLY WHEN A 4 STOP CONDITION DOES NOT EXIST.

REFERENCES

- 1. Oxman, Steven W., "Fiscal Year 1979 CCSMA System-Level Software Maintenance Approach and Transition Plan," March 20, 1979, (Revision E), Software Systems Department, Trident, CCSMA, New port, RI.
- Oxman, Steven W., "The Testing of the Trident Command and Control System," Workshop on Software Testing and Test Documentation, December 1978, Digest.
- 3. Chapin, Ned, "Flowcharting with the ANSI Standard: A Tutorial," Computing Surveys, ACM, June 1970, Volume 2, No. 2.

DISCLAIMER

The opinions expressed in this report are strictly those of the author and do not necessarily reflect the opinions of the Naval Postgraduate School, Department of the Navy, or Department of Defense.

DISTRIBUTION LIST

	No. Copies
Prof. Lyle Cox	1
Code 52Cl	
Computer Science Department	
Naval Postgraduate School	
Monterey, CA 93940	
Mr. William Ferreria	1
Trident CCSMA	
Building 12	
U.S. Navy	
Newport, RI 02840	
Mr. Gerald Goulet	1
Naval Air Development Center	
Warminster, PA 18974	
Prof. Carl R. Jones	1
Code 54Js	
Administrative Sciences Department	
Naval Postgraduate School	
Monterey, CA 93940	
Prof. Norman Lyons	1
Code 54Lb	
Administrative Sciences Department	
Naval Postgraduate School	
Monterey, CA 93940	
LCDR Ronald W. Modes	1
Code 52Mf	
Computer Science Department	
Naval Postgraduate School	
Monterey, CA 93940	
Mr. Steven Oxman	1
Trident CCSMA	
Building 132T	
U.S. Navy	
Newport, RI 02840	
Mr. Richard Pariseau	1
Naval Air Development Center	
Warminister, PA 18974	

	No. Copies
Prof. Norman F. Schneidewind Code 54Ss Administrative Sciences Department and Computer Science Department Naval Postgraduate School Monterey, CA 93940	10
Dr. John Stancil Trident CCSMA Building 132T U.S. Navy Newport, RI 02840	1
Prof. Roger Weissinger-Baylon Code 54Wr Administrative Sciences Department Naval Postgraduate School Monterey, CA 93940	1
AS/OR Library Code 54/55 Naval Postgraduate School Monterey, CA 93940	1
Computer Center Library Code 0141 Naval Postgraduate School Monterey, CA 93940	2
Computer Science Department Code 52 Naval Postgraduate School Monterey, CA 93940	2
Defense Technical Information Center Cameron Station Alexandria, VA 23314	2
Knox Library Code 0142 Naval Postgraduate School Monterey, CA 93940	4
Office of Research Administration Code 012A Naval Postgraduate School Monterey, CA 93940	1